

Aranet4 without Display

Wireless, portable device for measuring air quality. Measures carbon dioxide (CO_2) concentration, temperature, relative humidity, and atmospheric pressure. This device, belonging to the PRO sensor series, includes Aranet Sub-GHz ISM band radio which wirelessly transmits sensor measurements to the Aranet PRO base station.



Product numbers

Asia	TDSPC2U5	
United States	TDSPC2U5	
European Union	TDSPC205	

Sensor performance

General notes

- 95 % of the sensors perform within the specified accuracy limits at the time of purchase, assuming they are in an equilibrium state. For evaluation of the total measurement error, long-term drift has to be taken into account.
- Measurement time constant τ is determined at 1 m/s airflow. This constant refers to the time it takes for the sensor reading to reach 63 % of a new steady-state value in response to a step change in the environment. It essentially represents the speed at which the sensor adjusts to changes in the measured quantity.

CO₂ concentration

Range	0–9999 ppm
Resolution	1 ppm
Accuracy	±(30 ppm + 3 % of reading)
Long term drift	Not available
Time constant τ	100 s

CO₂ sensor of the device is calibrated at standard atmospheric pressure. CO₂ readings are pressure compensated
and comply with the specifications down to 750 hPa. If the device has to be used at high altitude for a prolonged
period of time, manual calibration of the unit should be performed for optimal performance. It is not intended to use
the device higher than 4000 m (13'000 ft) above the sea level.



- CO₂ measurement accuracy is provided for a range 0–5000 ppm, temperature 15–35 °C (59–95 °F) and relative humidity 0–80 %. Accuracy above 5000 ppm is 10 % of reading, but not guaranteed since it is extrapolated form the calibrated range.
- If a drift of the CO₂ measurements occurs, calibration feature of the device should be used. Auto calibration mode is utilizing ABC algorithm whereas manual calibration mode demands sensor to be exposed to fresh air.

Temperature

Range	0-50 °C	32–122°F
Resolution	0.1 °C	0.1 °F
Accuracy	±0.3 °C	±0.5°F
Long term drift	0.03 °C/year	0.05 °F/year
Time constant τ	10 min	

Relative humidity

Range	0–85 %
Resolution	1%
Accuracy	±3 %
Long term drift	0.5 %/year
Time constant τ	To be defined

Atmospheric pressure

Range	600-1100 hPa
Resolution	1hPa
Accuracy	+3 hPa / -2 hPa
Long term drift	1 hPa/year
Time constant τ	0 s (instantaneous)

[•] Device measures absolute pressure, i.e., readings are not compensated for an elevation above the sea level.

General specifications

IP20	
0-50 °C	32–122 °F
0–85 %	
71×71×24 mm	$2.80 \times 2.80 \times 0.94$ in
104 g	3.7 oz
10 mm	0.39 in
Polycarbonate	
2 pcs AA batteries	
2 pcs AA alkaline batteries, configuration pin	
	0–50 °C 0–85 % 71×71×24 mm 104 g 10 mm Polycarbonate 2 pcs AA batteries



Aranet radio parameters

Line of sight range	3 km	1.9 mi
Transmitter power	14 dBm	25 mW
Data transmission interval	1, 2, 5 or 10 min	
Data protection	XXTEA encryption	

Bluetooth parameters

Line of sight range	10 m	33 ft
Transmitter power	4 dBm or -12 dBm	
Data transmission interval	1, 2, 5 or 10 min	

Battery lifetime

Measurement interval	Alkaline battery lifetime	Lithium battery lifetime
1 min	2.1 years	2.8 years
2 min	3.8 years	5.2 years
5 min	8.0 years	>10 years
10 min	>10 years	>10 years

- Battery lifetime data has been obtained by mathematical extrapolation and is provided for descriptive purposes only and is not intended to make or imply any guarantee or warranty.
- Battery lifetime tests and calculations performed assuming device is at 20 °C (68 °F) and using *Fujitsu Premium LR6G07* (alkaline) and *Energizer Ultimate Lithium L91* (lithium) AA batteries as reference.
- The operating temperature range may vary based on the battery type used. Generally, the range for alkaline batteries is between -20-50 °C (-4-122 °F), whereas for lithium batteries, it is -40-60 °C (-40-140 °F).


Pairing process description

As part of the Aranet PRO product series, this device enables wireless sensor reading transmission to the Aranet PRO and PRO Plus base station. Here's how to pair the sensor with the base station:


- Place the sensor within 20 m (60 ft) of the base station during pairing. Once paired, it can communicate over a much greater distance (up to 3 km / 1.9 mi line of sight).
- If the sensor uses a power supply unit, unplug it. Open the sensor casing and remove the battery for at least 20 seconds. Alternatively (for newer hardware revisions), locate the PAIRING button on the sensor PCB which can be used to initiate pairing without the removal of battery.
- Access the SENSORS menu in the base station Web GUI. Set the measurement interval and select PAIR SENSOR to start the pairing process.



- Within a 2-minute window, insert the battery or press the PAIRING button on the sensor PCB (for newer hardware revisions) to initiate pairing.
- A successful pairing is indicated by the sensor appearing in the Web GUI and a specific LED blink sequence on the sensor PCB (one to three short blinks followed by a longer fade-out blink of the LED):



• If pairing fails, the sensor won't appear in the Web GUI, and the LED blink sequence will consist only of three short blinks. In this case, repeat the procedure closer to the base station.



• After successful pairing, customize parameters like name and tags in the Web GUI. Close the sensor casing and install it in the desired location.

Important notes

Device is qualified to work properly within ambient clean air. Qualification for use in harsh environment is the duty of
the user of the sensor. Exposure to volatile organic compounds, acids or bases, etching substances such as H₂O₂,
NH₃, shall be avoided.

Compliance information

C Conformité Européenne

Federal Communications Commission (USA)

IC Innovation, Science and Economic Development Canada